

Stainless Steel

Fastener

Protected
With TEF 45

Paint Blisters Filled With
Aluminum Oxide Powder
That Grow and Spread

ALUMINUM

Protected by
No Blisters
No Corrosion

MareLube

ALUMINUM

Galvanic Reaction & Aluminum Corrosion

Fastener

Unprotected Stainless Steel

Galvanic Corrosion Caused

BY Un-Protected Contact of

Dissimilar Metals Such as

Aluminum and Stainless Steel

Threaded Fasteners or Pop-Rivets